




October 17, 2011

MEMORANDUM

TO: District Board of Trustees
FROM: Jim Murdaugh, President 
SUBJECT: Annual SREF Update - October 2011

Item Description:

This item is a monthly update of the progress in correcting the SREF deficiencies as requested by the District Board of Trustees.

Overview:

The State Requirements for Educational Facilities, (SREF) mandates that the College perform annual safety inspections for all sites and facilities. All deficiencies and corrective actions have been addressed at the following sites: Main Campus, FPSI, Brogan Museum, Wakulla Center, CCLA, and Quincy House locations. At the Gadsden Center site, we are working with the respective lessees responsible for the corrective and/or remedial action pertaining to Fire Safety or Casualty/Sanitation deficiencies. Our initial contact at the county was not responsive so we have now contacted the Interim County Administrator, Mr. Lawson, to see if additional progress may be made.

Salient Facts:

All parts of the 2011 Annual SREF Fire, Sanitation, and Casualty Inspection have been completed and submitted with the exception of the Gadsden Center site. The Board requested a monthly update on the progress of these corrections until all items were complete.

Past Actions:

The District Board of Trustees has approved the inspection report.

Future Actions:

The District Board of Trustees will receive an update each month on the progress of the corrections. The attached report will be highlighted in yellow to indicate the item has been corrected.

Funding/Financial Matters:

All costs incurred to correct the deficiencies are funded from the Plant Operations Operating Budget and the annual PECO Maintenance allocation.

Staff Resource:

Teresa Smith

Recommended Action:
Provided as information only.



Florida Community Colleges Risk Management Consortium

5700 SW 34th Street • Suite 1205 • Gainesville, Florida 32608
(352) 955-2190 • Fax (352) 955-2069

November 4, 2010

MEMORANDUM

TO: Danny Taylor, Safety Specialist
Tallahassee Community College

FROM: Barbara Ellison *BGE*

SUBJECT: SREF Inspection

Attached is the Fire Safety, Sanitation and Casualty Inspection report for the 2010-2011 year which was performed by Walter Spann/Rich Carter of Fire Prevention Specialists, Inc on October 13, 2010 – October 19, 2010. If there are deficiencies noted on your SREF Inspection Report, please have your Facility Administrator sign the form where indicated at the bottom of the form.

The State Requirements for Educational Facilities (SREF) mandates that your annual Fire Safety, Casualty and Sanitation Inspection be submitted to your board no later than June 30th of each year. After board approval, a copy must be sent to the Florida State Fire Marshall's office and to Barbara Ellison at the following addresses:

Florida State Fire Marshall's Office
Scott Langston, Fire Prevention
200 East Gaines Street
Tallahassee, FL 32399-0342

FCSRMC
Barbara Ellison
5700 SW 34th Street, Suite 1205
Gainesville, FL 32608

If you have any questions on the inspection, please contact me.

Enclosure

CC: Jerry Schilling, Assistant VP, Administrative Services
Teresa Smith, VP, Chief Officer

**ANNUAL COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULE - SREF 2008 & F.A.C. 69A-58
FISCAL YEAR 2010-2011**

College Facility: Tallahassee Community College FIRE DISTRICT Tallahassee
 SCHOOL / FACILITY: Main Campus & Off Site Facilities
 ADDRESS: 444 Appleyard Drive, Tallahassee, FL 32304

OF SERIOUS FIRE SAFETY VIOLATIONS 0

OF NON-SERIOUS FIRE SAFETY VIOLATIONS 53

FIRE DISTRICT FIRE SAFETY INSPECTOR NAME PRINTED (IF JOINT INSPECTION): _____

Walter D. Spann, Jr., Rich Carter (Municipal Fire Safety Inspectors)
 SCHOOL BOARD FIRE SAFETY INSPECTOR NAME PRINTED

October 18, 2010
 INSPECTION DATE

FIRE DISTRICT FIRE SAFETY INSPECTOR SIGNATURE (IF JOINT INSPECTION): _____

Fire Prevention Specialists, Inc., 609 Gina Lane, Melbourne, FL 32940 321-757-7205
 INSPECTOR ADDRESS & PHONE NUMBER

SIGNATURE DATE FIRE INSPECTOR CERTIFICATION NUMBER _____

Walter D. Spann, Jr. Rich Carter 10-2-10
 COMM COLLEGE BOARD FIRE SAFETY INSPECTOR SIGNATURE / DATE

62373. 105523
 FIRE INSPECTOR CERTIFICATION NUMBER

LOCATION:

Deficiency locations will be identified by a building number followed by the room number (e.g. 2-505 or 1-133A). These numbers are usually the F.I.S.H. numbers affixed above the door leading into that particular room. Or if the deficiency in an area other than an identifiable room number, the area in question will be specifically identified. For example: Pressbox, Field House, Pavillion, etc.

Tallahassee Community College has met the requirements of F.S.S. 1013.12(2)(d): YES NO

The Local Fire District has met the requirements of F.S.S. 1013.12(3)(c) YES NO (Complete if Joint Inspection)

Approval of Reports by Board (Including Letter) YES NO

THE UNDERSIGNED ATTESTS TO THE REVIEW OF THIS REPORT IN ITS ENTIRETY AND ACKNOWLEDGES AWARENESS OF THE DISCOVERED DEFICIENCIES.

FACILITY ADMINISTRATOR NAME PRINTED _____

 FACILITY ADMINISTRATOR SIGNATURE

FACILITY ADMINISTRATOR TITLE _____

 SIGNATURE DATE

CODE NUMBER	Insp Initials	SREF 2010/2011 Fire Safety Deficiencies - Tallahassee Main Campus & Off Site Facilities				Prior Times Cited	Deficiency Corrected By	Date Deficiency Corrected	Master Code Violation Number	Line No
		Location, Deficiency Description								
FFPC 1, 12.3.2.1	WS	01-Elevator Equipment Room: Wall to ceiling joint to be fire caulked - east side				1	6-30-11	6-30-11	304	1
	WS	02-Building: No deficiencies noted							NVC	2
	WS	03-Building: No deficiencies noted							NVC	3
NFPA 70, Art. 314.28(C)	WS	04-Control Room: Open j-box at floor				1	6-30-11	2-18-11	808	4
NFPA 80, Art. 408.7	WS	05-124: Cover open slots in panel with proper covers at main switch				0	6-30-11	1-13-11	809	5
NFPA 72, 4.5.7	WS	05-152: FACP in "trouble" condition				0	6-30-11	1-13-11	407	6
FFPC 1, 11.1.5	WS	05-209: Improper use of extension cords				1	6-30-11	1-13-11	804	7
FFPC 1, 12.7.5.1	WS	05-Mezzanine: Conduit penetration from smoke detector to elevator to be sealed with UL listed fire caulk				1	6-30-11	1-13-11	304	8
FFPC 1, 13.3.3.3	WS	08-214A: Ceiling tile missing (sprinklered building)				0	6-30-11	1-18-11	559	9
FFPC 1, 12.5.7.1	WS	09-224: Floor conduit penetration to be sealed				0	6-30-11	1-13-11	304	10
NFPA 72, 5.7.4.1	WS	09-228: Smoke detector too close to A/C vent (to be >3')				1	6-30-11	6-30-11	499	11
FFPC 1, 12.5.7.1	WS	09-234: Floor conduit penetration to be sealed				0	6-30-11	1-13-11	304	12
NFPA 72, 5.4.3	WS	11-193: Detector hanging				0	6-30-11	6-30-11	499	13
FFPC 1, 13.6.6.8.3	WS	11-300: Fire extinguisher tag expired				0	6-30-11	1-24-11	501	14
NFPA 10, 6.3.2.2	WS	12-118: Fire extinguisher security tag missing				0	6-30-11	1-13-11	501	15
FFPC 1, 14.4.2	WS	12-210: Remove table and chairs in corridor				0	6-30-11	6-30-11	210	16
FFPC 1, 11.1.5.3.3	WS	12-Auditorium: Soundbooth - Power strip cord damaged under mixer				0	6-30-11	6-30-11	804	17
FFPC 1, 11.1.5.2.2	WS	12-Auditorium: Soundmixer at back of seating - multiple power strip and expansion cords plugged into each other				0	6-30-11	6-30-11	804	18
NFPA 80 2-1.4.1	WS	12-East Side of Stage: Exit door to East exit not latching				1	6-30-11	1-13-11	209	19
FFPC 1, 13.6.3.7	WS	12-Rear Stage Mezzanine: Fire extinguisher to be mounted				0	6-30-11	1-13-11	502	20
	WS	13-Building: To be removed							NVO	21
	WS	14-Building: To be removed							NVO	22
FFPC 1, 10.19.5.1	WS	15-Building: South Mechanical Room - Remove storage				0	6-30-11	6-30-11	808	23
NFPA 72, 4.5.7	WS	15-Boiler Room: FACP in "trouble" condition				0	6-30-11	1-13-11	407	24
NFPA 72, Ch. 10	WS	15-Boiler Room: FACP inspection expired				0	6-30-11	1-13-11	402	25
	WS	16-Building: No deficiencies noted							NVO	26
FFPC 1, 11.1.5.2.2	WS	17-138: Power strip plugged into extension cord				0	6-30-11	1-19-11	804	27
FFPC 1, 13.6.3.2	WS	18-129: No pressure in fire extinguisher				0	6-30-11	1-14-11	501	28
FFPC 1, 13.6.3.2	WS	18-135: No pressure in fire extinguisher				0	6-30-11	1-14-11	501	29
FFPC 1, 14.5.4.1	WS	18-202: Rated Chemical Storage Room door wedged open				1	6-30-11	6-30-11	209	30

CODE NUMBER	Type/Initials	SREF 2010/2011 Fire Safety Deficiencies - Tallahassee Main Campus & Off Site Facilities		Prior Times Cited	Deficiency Corrected By	Date Deficiency Corrected	Master Code Violation Number	Line No.
		Location	Deficiency Description					
FFPC 1, 11.1.5.2.2	WS	18-217:	Power strip plugged into extension cord	0	6-30-11	2-18-11	804	31
NFPA 30, 6.3.4	WS	18-Building:	improper venting of flammable storage cabinets (PVC not permitted - NFPA recommends no venting)	1	6-30-11	6-30-11	799	32
FFPC 1, 14.8.1.2	WS	18-Building:	Occupant load exceeded in most all general classrooms. Occ. Load may be increased with proper seating layout	0	6-30-11	6-30-11	102	33
NFPA 45, 8.13.1	WS	18-Labs:	Fume hoods to be inspected and tested annually	0	6-30-11	6-30-11	959	34
	RC	19-Building:	No deficiencies noted				NVO	35
FFPC 1, 14.5.2.0.2	RC	20-Building:	Practice area - Slide bolt lock on SE exit door	0	6-30-11	1-8-11	211	36
	RC	21-Building:	No deficiencies noted				NVO	37
	RC	22-Building:	No deficiencies noted				NVO	38
	RC	23-Building:	No deficiencies noted				NVO	39
	WS	27-Building:	No deficiencies noted				NVO	40
	WS	28-Building:	No deficiencies noted				NVO	41
	WS	29-Building:	to be demolished				NVO	42
FFPC 1, 11.1.5.2.2	WS	30-107:	Power strips linked together to extension cord	0	6-30-11	1-13-11	804	43
FFPC 1, 10.19.3.1	WS	30-172:	Remove storage from center racks to 2' below ceiling	1	6-30-11	2-10-11	901	44
FFPC 1, 11.1.5.2.2	WS	30-227:	Several power strips linked together	0	6-30-11	1-13-11	804	45
	RC	31-Building:	No deficiencies noted				NVO	46
	RC	32-Building:	No deficiencies noted				NVO	47
	RC	33-Building:	No deficiencies noted				NVO	48
FFPC 1, 14.4.2.1	RC	34-100:	Corridor and exit door obstructed with storage	1	6-30-11	1-14-11	210	49
NFPA 72, Ch.10	RC	34-Building:	Hal - Fire alarm inspection overdue	0	6-30-11	1-14-11	402	50
FFPC 1, 14.4.2.1	RC	34-Building:	Practice area - Exit door obstructed with shelves	0	6-30-11	1-14-11	211	51
FFPC 1, 11.1.5.2.2	WS	35-119:	Power strip plugged into orange cord through doorway	0	6-30-11	1-14-11	804	52
FFPC 1, 6.3.3.1.4.4	WS	35-188:	Unsecured gas cylinder	1	6-30-11	6-30-11	704	53
FFPC 1, 11.1.5.2.2	WS	35-Bookstore:	Power strip plugged into orange extension cord at upper level computer next to Room 121	0	6-30-11	1-19-11	804	54
FFPC 1, 11.1.5.2.2	WS	35-Bookstore:	Power strip plugged into power strip plugged into orange extension cord at Textbook Office	0	6-30-11	1-19-11	804	55
FFPC 1, 14.4.2.1	RC	36-100:	Bookcase obstructing required egress width	1	6-30-11	1-10-11	210	56
FFPC 101, 4.5.7	RC	35-Mezzanine:	Battery powered smoke detector inoperable	1	6-30-11	1-13-11	499	57
FFPC 1, 12.5.7.1	RC	38-108:	Two sleeves at ceiling require fire caulk	1	6-30-11	1-25-11	304	58
NFPA 72, 5.4.3	RC	38-By Room 223A:	Smoke detector hanging from base	0	6-30-11	1-13-11	499	59
NFPA 72, Ch. 10	RC	38-Lobby:	Fire alarm inspection overdue	0	6-30-11	1-16-11	402	60

CODE NUMBER	Insp. Initials	SREF 2010/2011 Fire Safety Deficiencies - Tallahassee Main Campus & Off Site Facilities				Pnor Times Cited	Deficiency Corrected By	Date Deficiency Corrected	Master Code Violation Number	Line No
		Location, Deficiency Description								
	RC	39-Building. No deficiencies noted							NVO	61
NFPA 80, 15-2.5.3	RC	41-238: Fire rated roll-up door inoperable				0	6-30-11	1-16-11	209	62
	RC	42-Building. No deficiencies noted							NVO	63
	RC	43-Building. Less than one year old							NVO	64
	RC	44-Building. No deficiencies noted							NVO	65
	RC	45-Building. No deficiencies noted							NVO	66
	RC	46-Building. No deficiencies noted							NVO	67
	RC	47-Building. No deficiencies noted							NVO	68
FFPC 1, 11.1.3	RC	49-Mezzanine: Romex wiring running across floor				1	6-30-11	6-30-11	804	69
NFPA 70, Art 110.26	RC	49-NE. Electrical pane- obstructed				1	6-30-11	1-18-11	801	70
FFPC 1, 13.6.3.7	RC	49-North Bay: Fire extinguisher to be mounted				0	6-30-11	1-18-11	502	71
NFPA 70, Art. 314.25	RC	49-North Bay. West wall - electrical panel off				0	6-30-11	1-18-11	809	72
FFPC 1, 11.1.5	RC	49-Throughout: Extension cords used as permanent wiring				1	6-30-11	6-30-11	804	73
NFPA 72, Ch.10	RC	50-Hall: Fire alarm inspection overdue				0	6-30-11	6-30-11	402	74
	RC	52-Building. No deficiencies noted							NVO	75
	RC	53-Building. No deficiencies noted							NVC	76
FFPC 1, 10.19.3	RC	54-Center: Storage to be maintained below 2' from ceiling				1	6-30-11	1-14-11	901	77
NFPA 70, Art 314.28(c)	RC	54-Electric cage: Open j-box (x3)				0	6-30-11	1-13-11	809	78
NFPA 25, 4.6	RC	55-Building. Red tag on sprinkler system				0	6-30-11	2-28-11	589	79
NFPA 72, Ch.10	RC	56-NW Fire alarm system dysfunctional - Bldg. 55 sprinkler tied to this FACD				1	6-30-11	2-28-11	410	80
FFPC 1, 63.3.1.4.4	RC	57-Loading Dock Propane tanks not secured				0	6-30-11	1-14-11	702	81
	RC	58-Building. No deficiencies noted							NVC	82
NFPA 14, 4.7.3	WS	Parking garage. Cap missing on standpipe valve at NE stair				1	6-30-11	1-13-11	599	83
NFPA 72, Ch.10	WS	Parking Garage: Fire Alarm inspection past due				0	6-30-11	1-14-11	402	84

**ANNUAL COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULE - SREF 2008 & F.A.C. 69A-58
FISCAL YEAR 2010-2011**

College Facility: Tallahassee Community College FIRE DISTRICT: Gadsden County
 SCHOOL / FACILITY: Pat Thomas Law Enforcement Academy
 ADDRESS: Hwy 90, Quincy, FL 32333

OF SERIOUS FIRE SAFETY VIOLATIONS 0
 # OF NON-SERIOUS FIRE SAFETY VIOLATIONS 15

FIRE DISTRICT FIRE SAFETY INSPECTOR NAME (PRINTED IF JOINT INSPECTION): _____

Walter D. Spann, Jr. (Municipal Fire Safety Inspector)
 SCHOOL BOARD FIRE SAFETY INSPECTOR NAME (PRINTED)

October 13, 2009
 INSPECTION DATE

FIRE DISTRICT FIRE SAFETY INSPECTOR SIGNATURE (IF JOINT INSPECTION): _____

Fire Prevention Specialists, Inc., 609 Gina Lane, Melbourne, FL 32940 321-757-7205
 INSPECTOR ADDRESS & PHONE NUMBER

SIGNATURE DATE FIRE INSPECTOR CERTIFICATION NUMBER

Walter D. Spann, Jr. 11-2-10
 COMM. COLLEGE BOARD FIRE SAFETY INSPECTOR SIGNATURE / DATE

62373
 FIRE INSPECTOR CERTIFICATION NUMBER

LOCATION:

Deficiency locations will be identified by a building number followed by the room number (e.g. 2-505 or 1-133A). These numbers are usually the F.I.S.H. numbers affixed above the door leading into that particular room. Or if the deficiency in an area other than an identifiable room number, the area in question will be specifically identified. For example: Pressbox, Field House, Pavilion, etc.

Tallahassee Community College has met the requirements of F.S.S. 1013.12(2)(d): YES NO

The Local Fire District has met the requirements of F.S.S. 1013.12(3)(c) YES NO (Complete if Joint Inspection)

Approval of Reports by Board (Including Letter) YES NO

THE UNDERSIGNED ATTESTS TO THE REVIEW OF THIS REPORT IN ITS ENTIRETY AND ACKNOWLEDGES AWARENESS OF THE DISCOVERED DEFICIENCIES.

FACILITY ADMINISTRATOR NAME (PRINTED) _____

FACILITY ADMINISTRATOR SIGNATURE _____

FACILITY ADMINISTRATOR TITLE _____

SIGNATURE DATE _____

**ANNUAL COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULE - SREF 2008 & F.A.C. 69A-58
FISCAL YEAR 2010-2011**

College Facility: Tallahassee Community College FIRE DISTRICT: Various
 SCHOOL / FACILITY: Satellite Facilities and Leased Facilities # OF SERIOUS FIRE SAFETY VIOLATIONS 0
 ADDRESS: 444 Appleyard Drive, Tallahassee, FL 32304 # OF NON-SERIOUS FIRE SAFETY VIOLATIONS 32

FIRE DISTRICT FIRE SAFETY INSPECTOR NAME PRINTED (IF JOINT INSPECTION) Walter D. Spann, Jr., Rich Carter (Municipal Fire Safety Inspectors) INSPECTION DATE October 19, 2010
 SCHOOL BOARD FIRE SAFETY INSPECTOR NAME PRINTED
 FIRE DISTRICT FIRE SAFETY INSPECTOR SIGNATURE (IF JOINT INSPECTION) Fire Prevention Specialists, Inc., 609 Gina Lane, Melbourne, FL 32940 321-757-7205
 INSPECTOR ADDRESS & PHONE NUMBER
 SIGNATURE / DATE [Signature] FIRE INSPECTOR CERTIFICATION NUMBER 62373, 105523
 FIRE INSPECTOR CERTIFICATION NUMBER

LOCATION:

Deficiency locations will be identified by a building number followed by the room number (e.g. 2-505 or 1-133A). These numbers are usually the F.I.S.H. numbers affixed above the door leading into that particular room. Or if the deficiency in an area other than an identifiable room number, the area in question will be specifically identified. For example: Pressbox, Field House, Pavilion, etc.

Tallahassee Community College has met the requirements of F.S.S. 1013.12(2)(d): YES ___ NO

The Local Fire District has met the requirements of F.S.S. 1013.12(3)(c) ___ YES ___ NO (Complete if Joint Inspection)

Approval of Reports by Board (Including Letter) ___ YES ___ NO

THE UNDERSIGNED ATTESTS TO THE REVIEW OF THIS REPORT IN ITS ENTIRETY AND ACKNOWLEDGES AWARENESS OF THE DISCOVERED DEFICIENCIES.

FACILITY ADMINISTRATOR NAME PRINTED _____

FACILITY ADMINISTRATOR SIGNATURE _____

FACILITY ADMINISTRATOR TITLE _____

SIGNATURE DATE _____

CODE NUMBER	Insp. Initials:	SREF 2010/2011 Fire Safety Deficiencies - TCC Satellite & Leased Facilities	Prior Times Cited	Deficiency Corrected By	Date Deficiency Corrected	Master Code Violation Number	Line No.
		Location, Deficiency Description					
NFPA 72, 4.4.3.5	RC	Brogan Museum, 1st Floor Electrical Room: FACP in "trouble" condition	0	6-30-11	1-14-11	407	1
FFPC 1, 14.4.2.1	RC	Brogan Museum, 1st Floor, NW exit: Debris blocking door from completely opening	0	6-30-11	1-14-11	210	2
FFPC 1, 4.5.8.1	RC	Brogan Museum, 3rd Floor NW Exit light inoperative	0	6-30-11	1-14-11	202	3
							4
FFPC 1, 4.3.6.8.3	RC	Wakulla Center Throughout: All fire extinguisher inspection tags expired	1	6-30-11	6-30-11	501	5
NFPA 72 Ch.10	RC	Wakulla Center SW: Fire alarm system inspection not current	1	6-30-11	6-30-11	410	6
							7
NFPA 70, Art. 110.28	RC	CCLA North Hall Closet: Electrical panels obstructed	1	6-30-11	6-30-11	801	8
NFPA 70, Art. 110.26	RC	CCLA W-14: Many electrical panels obstructed	1	6-30-11	6-30-11	801	9
							10
FFPC 1, 4.5.8.1	RC	Quincy House 1st Floor Hall: Exit light battery dead	0	6-30-11	6-30-11	202	11
FFPC 1, 4.5.8.1	RC	Quincy House Room 108: Exit light inoperative	0	6-30-11	6-30-11	202	12
NFPA 70, Art. 110.26	RC	Quincy House, Room 106: Table and banner obstructing electrical and FACP pane close;	0	6-30-11	6-30-11	801	13
							14
FFPC 1, 4.5.8.1	WS	Gadsden Center: Exit sign out in Lobby, 3rd Floor Conference Room Room 128	1	6-30-11		202	15
NFPA 1962 Ch. 4 & 5	WS	Gadsden Center: General: Fire hose in cabinets to be inspected	1	6-30-11		599	16
NFPA 72, 4.4.3.5	WS	Gadsden Center: FACP in "trouble" condition (all: no update/reports from Bldg. Manager)	1	6-30-11		409	17
FFPC 1, 11.1.5	WS	Gadsden Center: Mechanical Room 129: Power strip plugged into extension cord	1	6-30-11		804	18
FFPC 1, 14.4.2.1	WS	Gadsden Center: Remove storage on South Stair landing	1	6-30-11		210	19
FFPC 1, 4.5.8.1	WS	Gadsden Center: No break glass hammer for valve cabinet at First Floor Center Stair landing	1	6-30-11		599	20
NFPA 25, 4.6	RC	Gadsden Center, Boiler Room: Red tag on sprinkler system	0	6-30-11		599	21
NFPA 25, 4.6	RC	Gadsden Center, Boiler Room: Drain from fire pump bearing drip stopped up	0	6-30-11		599	22
69A-51.050(2)	RC	Gadsden Center, Boiler Room: Boiler inspection certificate not located	0	6-30-11		796	23
FFPC 1, 13.3.3.3	RC	Gadsden Center, Ground Floor: Ceiling tile missing adjacent to Men's Room: (sprinklered building)	0	6-30-11		599	24
FFPC 1, 4.5.8.1	RC	Gadsden Center, Room G-99: Exit light inoperative	0	6-30-11		202	25
NFPA 2001, 6.1.1	RC	Gadsden Center, Server Room: FM 200 system inspection overdue	0	6-30-11		516	26
NFPA 80, 15-2.3.3	RC	Gadsden Center, 1st Floor adjacent to elevator: Fire door propped open	0	6-30-11		209	27
FFPC 1, 13.3.3.2	RC	Gadsden Center, 1st Floor S. Stair: Pre-action system inspection overdue	0	6-30-11		516	28
FFPC 1, 13.3.3.3	RC	Gadsden Center, Room 112: Ceiling tile missing (sprinklered building)	0	6-30-11		599	29
FFPC 1, 11.1.5.2.2	RC	Gadsden Center, Room 127: Power strips linked together	0	6-30-11		804	30

