




November 20, 2017

MEMORANDUM

TO: District Board of Trustees
FROM: Jim Murdaugh, President 
SUBJECT: Project Priority List (PPL)

Item Description

This item requests approval of the attached Project Priority List for expenditure of Capital Outlay and Debt Service (CO & DS) funds received from the Department of Education.

Overview and Background

The Department of Education annually disburses CO & DS funds to Tallahassee Community College. The College is required to expend these funds in accordance with an approved plan referred to as the Project Priority List (PPL). The projects included in the PPL must be recommended in TCC's Five Year Educational Plant Survey

Draft copies of the updated document is attached for review and approval. After approval by the District Board of Trustees, the draft documents will be electronically submitted for approval to the Department of Education through their online system, Educational Facilities Information System (EFIS).

Past Actions by the Board

The Board approved the last Project Priority List on November 19, 2012.

Funding/Financial Implications

The approved PPL allows the expenditure of annual CO & DS funds on key projects that support the educational mission of the College.

Staff Resource

Barbara Wills

Recommended Action

Approve the attached Project Priority List in preparation for transmittal to DOE.

FLORIDA COLLEGE SYSTEM

PROJECT PRIORITY LIST REPORT

TALLAHASSEE COMMUNITY COLLEGE

SURVEY: Number 2 - Version 1

Survey Board Approval Date: 8/15/2016

PPL Number:

PPL Board Approval Date: 4/26/2017

PPL Status: Submitted

PPL DOE Approval Date:

In accordance with the provisions of Section (9)(d), Article XII, State Constitution, relating to the order of priority for the expenditure of funds known as capital outlay and debt service (CO&DS) funds, the TALLAHASSEE COMMUNITY COLLEGE certifies that this list of projects and the order of priority assigned are based on a survey dated as required by Section 1013.31, F.S., the Florida Administrative Code, Section 6A-2.0010, State Requirements for Educational Facilities (SREF), and are consistent with the capital outlay needs of the college. As CO&DS funds are made available, the Board proposes to carry out these projects as nearly as practicable in the order given, subject to changes provided in state law, the Florida Administrative Code, and SREF.

Project Number: 1		No Comments Provided			
Project Number	Priority Ranking	Description	Estimated Cost	Status	Completed Date
1	A	Site: 1 MAIN CAMPUS Survey Recommendation: 1.001 Repair and upgrade exterior lighting at both pedestrian and vehicle areas for better safety.	\$300,000.00		
1	A	Site: 1 MAIN CAMPUS Survey Recommendation: 1.002 Campus-wide life safety and health repairs, including sidewalks, ADA compliance, fire alarm, doors and hardware.	\$600,000.00		
1	A	Site: 1 MAIN CAMPUS Survey Recommendation: 1.003 Upgrades to telecommunications and data systems, including fiber, networks, switches and related items.	\$2,000,000.00		
1	A	Site: 1 MAIN CAMPUS Survey Recommendation: 1.004 Repairs and upgrades to boilers, chillers, piping, controls and related systems campus-wide to improve efficiency and operation.	\$8,000,000.00		

FLORIDA COLLEGE SYSTEM
PROJECT PRIORITY LIST REPORT
TALLAHASSEE COMMUNITY COLLEGE

Project Number: 1		No Comments Provided			
Project Number	Priority Ranking	Description	Estimated Cost	Status	Completed Date
1	A	Site: 1 MAIN CAMPUS Survey Recommendation: 1.005 Upgrade and repair parking lots including drainage improvements, resurfacing, restriping and signs.	\$400,000.00		
1	A	Site: 1 MAIN CAMPUS Survey Recommendation: 1.006 Repair and replace existing roof systems to correct deterioration and roof leaks.	\$400,000.00		
1	A	Site: 1 MAIN CAMPUS Survey Recommendation: 1.007 Repair and upgrade recently purchased parcels to include paving, drainage and landscaping.	\$750,000.00		
1	A	Site: 1 MAIN CAMPUS Survey Recommendation: 1.008 Upgrade landscaping, hardscape features, irrigation and controls.	\$50,000.00		
1	A	Site: 1 MAIN CAMPUS Survey Recommendation: 1.009 Repairs and upgrades to exterior and interior signage.	\$100,000.00		
1	A	Site: 1 MAIN CAMPUS Survey Recommendation: 1.010 Repair and upgrade existing storm water sites for improvements. Identify all areas that do not drain properly and renovate in accordance with the Master Plan.	\$82,000.00		
1	A	Site: 1 MAIN CAMPUS Survey Recommendation: 1.011 Acquire land and facilities proximate to main campus.	\$2,500,000.00		

FLORIDA COLLEGE SYSTEM
PROJECT PRIORITY LIST REPORT
TALLAHASSEE COMMUNITY COLLEGE

Project Number: 1		No Comments Provided			
Project Number	Priority Ranking	Description	Estimated Cost	Status	Completed Date
1	A	Site: 1 MAIN CAMPUS Survey Recommendation: 1.012 Renovating Building Number - 54, Building Name - VACANT BUILDING (0 SS), (14494 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 00100 (1998 NSF), Room 00101 (328 NSF), Room 00102 (77 NSF), Room 00103 (104 NSF), Room 00103A (70 NSF), Room 00103B (40 NSF), Room 00104 (408 NSF), Room 00104A (100 NSF), Room 00104B (40 NSF), Room 00110 (25 NSF), Room 00110B (25 NSF), Room 00111 (238 NSF), Room 00112 (282 NSF), Room 00113 (228 NSF), Room 00113A (69 NSF), Room 00113C (607 NSF), Room 00115 (125 NSF), Room 00116 (120 NSF), Room 00116B (50 NSF), Room 00117 (1316 NSF), Room 00118 (391 NSF), Room 00119 (129 NSF), Room 00120 (211 NSF), Room 00122 (299 NSF), Room 00123 (228 NSF), Room 00124 (236 NSF), Room 00125 (244 NSF), Room 00126 (575 NSF), Room 00126A (350 NSF), Room 00126B (160 NSF), Room 00127 (144 NSF), Room 00127A (142 NSF), Room 00128 (144 NSF), Room 00129 (877 NSF), Room 00130 (109 NSF), Room 00132 (115 NSF), Room 00133 (575 NSF), Room 00134 (843 NSF), Room 00136 (115 NSF), Room 00201 (391 NSF), Room 00202 (144 NSF), Room 00203 (142 NSF), Room 00204 (231 NSF), Room 00205 (278 NSF), Room 00207A (48 NSF), Room 00208 (88 NSF), Room 00210 (88 NSF), Room 00210A (196 NSF), Room 00210B (98 NSF), Room 00211 (178 NSF), Room 00212 (272 NSF), Room 00213 (61 NSF), Room 00213A (142 NSF)	\$1,304,460.00		

FLORIDA COLLEGE SYSTEM
PROJECT PRIORITY LIST REPORT
TALLAHASSEE COMMUNITY COLLEGE

Project Number: 1		No Comments Provided			
Project Number	Priority Ranking	Description	Estimated Cost	Status	Completed Date
1	A	Site: 1 MAIN CAMPUS Survey Recommendation: 1.013 Renovating Building Number - 56, Building Name - FUTURE PLANT OPERATI (0 SS), (13068 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 00100 (1604 NSF), Room 00101 (1248 NSF), Room 00102 (100 NSF), Room 00104 (2720 NSF), Room 00105 (178 NSF), Room 00106 (124 NSF), Room 00107 (116 NSF), Room 00108 (334 NSF), Room 00109 (148 NSF), Room 00110 (170 NSF), Room 00111 (116 NSF), Room 00112 (1966 NSF), Room 00112A (168 NSF), Room 00112B (60 NSF), Room 00112C (180 NSF), Room 00113 (116 NSF), Room 00114 (213 NSF), Room 00115 (138 NSF), Room 00116 (286 NSF), Room 00117 (298 NSF), Room 00118 (381 NSF), Room 00119 (723 NSF), Room 00121 (59 NSF), Room 00122 (319 NSF), Room 00123 (609 NSF), Room 00125 (404 NSF), Room 00126 (290 NSF)	\$1,176,120.00		
1	A	Site: 1 MAIN CAMPUS Survey Recommendation: 1.014 Renovating Building Number - 42, Building Name - HUGHES EAST (0 SS), (18103 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room00117 (534 NSF), Room 00100 (1573 NSF), Room 00101 (53 NSF), Room 00104 (24 NSF), Room 00105 (455 NSF), Room 00106 (164 NSF), Room 00107 (167 NSF), Room 00108 (480 NSF), Room 00109 (9435 NSF), Room 00110 (121 NSF), Room 00111 (3380 NSF), Room 00112 (651 NSF), Room 00115 (533 NSF), Room 00116 (533 NSF)	\$1,629,270.00		
1	A	Site: 1 MAIN CAMPUS Survey Recommendation: 1.015 Renovating Building Number - 35, Building Name - STUDENT UNION (0 SS), (82996 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 00001 (400 NSF), Room 00100 (1144 NSF), Room 00100E (42 NSF), Room 00101 (575 NSF), Room 00102 (1196 NSF), Room 00103 (1896 NSF), Room 00104 (5627 NSF), Room 00105 (1034 NSF), Room 00106 (1027 NSF), Room 00107	\$7,469,640.00		

FLORIDA COLLEGE SYSTEM
PROJECT PRIORITY LIST REPORT
TALLAHASSEE COMMUNITY COLLEGE

(1027 NSF), Room 00108 (243 NSF), Room 00112A (29 NSF), Room 00113A (29 NSF), Room 00114 (424 NSF), Room 00115 (7070 NSF), Room 00120 (1091 NSF), Room 00121 (120 NSF), Room 00121A (120 NSF), Room 00122 (243 NSF), Room 00150 (2943 NSF), Room 00151 (123 NSF), Room 00151A (63 NSF), Room 00153 (724 NSF), Room 00153A (72 NSF), Room 00154 (203 NSF), Room 00155 (182 NSF), Room 00156 (132 NSF), Room 00157 (148 NSF), Room 00158 (151 NSF), Room 00159 (145 NSF), Room 00160 (243 NSF), Room 00162 (251 NSF), Room 00163 (151 NSF), Room 00164 (761 NSF), Room 00165 (172 NSF), Room 00165A (30 NSF), Room 00166 (1627 NSF), Room 00166A (921 NSF), Room 00167 (1343 NSF), Room 00167A (852 NSF), Room 00168A (32 NSF), Room 00170A (39 NSF), Room 00172 (470 NSF), Room 00173 (450 NSF), Room 00174 (248 NSF), Room 00175 (117 NSF), Room 00176 (117 NSF), Room 00177 (234 NSF), Room 00178 (263 NSF), Room 00179 (241 NSF), Room 00181 (71 NSF), Room 00182 (836 NSF), Room 00183 (455 NSF), Room 00184 (91 NSF), Room 00185 (875 NSF), Room 00186 (88 NSF), Room 00186A (86 NSF), Room 00187 (101 NSF), Room 00188 (100 NSF), Room 00189 (724 NSF), Room 00190 (517 NSF), Room 00190A (559 NSF), Room 00191 (593 NSF), Room 00192 (615 NSF), Room 00193 (488 NSF), Room 00194 (243 NSF), Room 00198 (366 NSF), Room 00200 (1540 NSF), Room 00201 (155 NSF), Room 00202 (352 NSF), Room 00202X (243 NSF), Room 00203 (348 NSF), Room 00203X (243 NSF), Room 00204 (122 NSF), Room 00204X (253 NSF), Room 00205 (181 NSF), Room 00205X (243 NSF), Room 00206 (1908 NSF), Room 00206X (366 NSF), Room 00207 (439 NSF), Room 00207A (387 NSF), Room 00208 (688 NSF), Room 00209 (727 NSF), Room 00209A (584 NSF), Room 00211 (67 NSF), Room 00212 (302 NSF), Room 00212A (351 NSF), Room 00213 (246 NSF), Room 00214 (165 NSF), Room 00215 (166 NSF), Room 00216 (263 NSF), Room 00217 (148 NSF), Room 00218 (165 NSF), Room 00219 (160 NSF), Room 00220 (139 NSF), Room 00221 (169 NSF), Room 00222 (146 NSF), Room 00223 (138 NSF), Room 00224 (145 NSF), Room 00225 (140 NSF), Room 00226 (139 NSF), Room 00227 (139 NSF), Room 00228 (851 NSF), Room 00228A (172 NSF), Room 00229A (29 NSF), Room 00230A (29 NSF), Room 00231 (315 NSF), Room 00232 (517 NSF), Room 00233 (150 NSF), Room 00234 (150 NSF), Room 00235 (148 NSF), Room 00236 (150 NSF), Room 00237 (212 NSF), Room 00238 (150 NSF), Room 00239 (148 NSF), Room 00240 (130 NSF), Room 00241 (152 NSF), Room 00242 (500 NSF), Room 00243 (500 NSF), Room 00245 (2086 NSF), Room 00246 (615 NSF), Room 00247 (766 NSF), Room 00247A (583 NSF), Room 00248 (285 NSF), Room 00249 (420 NSF), Room 00250 (394 NSF), Room 00250A (219 NSF), Room 00251 (80 NSF), Room 00252 (145 NSF), Room 00253 (148 NSF), Room 00254 (196 NSF), Room 00255 (140 NSF), Room 00256 (131 NSF),

FLORIDA COLLEGE SYSTEM
PROJECT PRIORITY LIST REPORT
TALLAHASSEE COMMUNITY COLLEGE

	<p>Room 00257 (131 NSF), Room 00258 (140 NSF), Room 00259 (156 NSF), Room 00260 (548 NSF), Room 00261 (628 NSF), Room 00261A (129 NSF), Room 00262 (492 NSF), Room 00262A (126 NSF), Room 00264 (142 NSF), Room 00265 (145 NSF), Room 00266 (144 NSF), Room 00267 (140 NSF), Room 00268 (179 NSF), Room 00269 (218 NSF), Room 00270 (216 NSF), Room 00270A (107 NSF), Room 00271 (195 NSF), Room 00272 (347 NSF), Room 00272A (170 NSF), Room 00273 (661 NSF), Room 00273A (141 NSF), Room 00273B (487 NSF), Room 00274 (383 NSF), Room 00275 (274 NSF), Room 00276 (104 NSF), Room 00277 (175 NSF), Room 00278 (684 NSF), Room 00278A (227 NSF), Room 00279 (188 NSF), Room 00280 (126 NSF), Room 00281 (644 NSF), Room 00281A (129 NSF), Room 00282 (76 NSF), Room 00283 (113 NSF), Room 00284 (127 NSF), Room 00285 (127 NSF), Room 00286 (172 NSF), Room 00287 (140 NSF), Room 00288 (163 NSF), Room 00289 (159 NSF), Room 00290 (347 NSF), Room 00291 (780 NSF), Room 00292 (145 NSF), Room 00293 (145 NSF), Room 00294 (145 NSF), Room 00295 (250 NSF), Room 00296 (396 NSF), Room 00298A (32 NSF), Room 00299A (39 NSF), Room 00301 (4993 NSF)</p>			
1	<p>A Site: 1 MAIN CAMPUS Survey Recommendation: 1.016 Renovating Building Number - 27, Building Name - HINSON ADMINISTRATIO (0 SS), (37215 NSF) Apply Painting, Floor Cover, Windows, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Other to Room 00100 (2134 NSF), Room 00100A (63 NSF), Room 00101 (171 NSF), Room 00102 (143 NSF), Room 00103 (153 NSF), Room 00104 (167 NSF), Room 00105 (144 NSF), Room 00106 (146 NSF), Room 00107 (118 NSF), Room 00108 (211 NSF), Room 00110 (246 NSF), Room 00111 (177 NSF), Room 00112 (190 NSF), Room 00113 (266 NSF), Room 00114 (125 NSF), Room 00115 (702 NSF), Room 00116 (72 NSF), Room 00117 (475 NSF), Room 00118 (150 NSF), Room 00119 (184 NSF), Room 00120 (308 NSF), Room 00121 (88 NSF), Room 00125 (180 NSF), Room 00127 (325 NSF), Room 00128 (258 NSF), Room 00134 (549 NSF), Room 00135 (82 NSF), Room 00138 (199 NSF), Room 00139 (143 NSF), Room 00140 (225 NSF), Room 00141 (133 NSF), Room 00142 (136 NSF), Room 00143 (139 NSF), Room 00144 (142 NSF), Room 00145 (170 NSF), Room 00146 (274 NSF), Room 00148 (317 NSF), Room 00149 (315 NSF), Room 00150 (534 NSF), Room 00151 (277 NSF), Room 00154 (330 NSF), Room 00155 (123 NSF), Room 00156 (292 NSF), Room 00156A (154 NSF), Room 00156B (151 NSF), Room 00157 (117 NSF), Room 00157A (152 NSF), Room 00157B (127 NSF), Room 00157C (115 NSF), Room 00157D (116 NSF), Room 00158 (180 NSF), Room 00159 (355 NSF), Room 00160 (66 NSF), Room 00161 (75 NSF), Room 00162 (94 NSF), Room 00165 (245 NSF), Room 00166 (320 NSF), Room 00167</p>	\$3,349,350.00		

FLORIDA COLLEGE SYSTEM
PROJECT PRIORITY LIST REPORT
TALLAHASSEE COMMUNITY COLLEGE

		<p>(300 NSF), Room 00168 (537 NSF), Room 00169 (174 NSF), Room 00170 (128 NSF), Room 00171 (404 NSF), Room 00174 (127 NSF), Room 00176 (95 NSF), Room 00177 (95 NSF), Room 00178 (151 NSF), Room 00178A (95 NSF), Room 00179 (156 NSF), Room 00179A (93 NSF), Room 00179B (93 NSF), Room 00180 (222 NSF), Room 00181 (95 NSF), Room 00182 (110 NSF), Room 00183 (133 NSF), Room 00184 (171 NSF), Room 00184A (261 NSF), Room 00184B (201 NSF), Room 00184C (74 NSF), Room 00186A (29 NSF), Room 00187 (256 NSF), Room 00188 (228 NSF), Room 00190 (549 NSF), Room 00190A (223 NSF), Room 00191 (78 NSF), Room 00193 (134 NSF), Room 00193A (531 NSF), Room 00193B (51 NSF), Room 00193C (128 NSF), Room 00193D (352 NSF), Room 00193E (390 NSF), Room 00193F (132 NSF), Room 00193G (136 NSF), Room 00193H (240 NSF), Room 00193I (140 NSF), Room 00193J (212 NSF), Room 00193K (149 NSF), Room 00194 (282 NSF), Room 00195 (169 NSF), Room 00195A (152 NSF), Room 00196 (333 NSF), Room 00197 (200 NSF), Room 00201 (1864 NSF), Room 00201A (85 NSF), Room 00202 (1053 NSF), Room 00202A (419 NSF), Room 00202B (447 NSF), Room 00203 (122 NSF), Room 00204 (438 NSF), Room 00205 (287 NSF), Room 00206 (191 NSF), Room 00207 (551 NSF), Room 00207A (196 NSF), Room 00208 (169 NSF), Room 00209 (176 NSF), Room 00210 (162 NSF), Room 00211 (131 NSF), Room 00212 (182 NSF), Room 00213 (157 NSF), Room 00214 (302 NSF), Room 00214A (270 NSF), Room 00215 (57 NSF), Room 00217 (225 NSF), Room 00218 (185 NSF), Room 00218A (118 NSF), Room 00218B (79 NSF), Room 00219 (292 NSF), Room 00220 (148 NSF), Room 00221 (148 NSF), Room 00222 (208 NSF), Room 00223 (148 NSF), Room 00224 (162 NSF), Room 00224A (191 NSF), Room 00225 (228 NSF), Room 00226 (148 NSF), Room 00227 (335 NSF), Room 00227A (112 NSF), Room 00227B (124 NSF), Room 00228 (256 NSF), Room 00229 (16 NSF), Room 00230 (45 NSF), Room 00232 (183 NSF), Room 00235 (336 NSF), Room 00236 (252 NSF), Room 00237 (321 NSF), Room 00239 (208 NSF), Room 00240 (527 NSF), Room 00242 (26 NSF), Room 00243 (333 NSF), Room 00247 (36 NSF), Room 00248 (276 NSF), Room 00249 (226 NSF), Room 00250 (132 NSF), Room 00251 (187 NSF), Room 00252 (66 NSF), Room 00253 (134 NSF), Room 00254 (191 NSF), Room 00255 (141 NSF), Room 00256 (155 NSF), Room 00257 (142 NSF), Room 00258 (40 NSF), Room 00260 (139 NSF), Room 00261 (85 NSF)</p>			
1	A	<p>Site: 1 MAIN CAMPUS Survey Recommendation: 1.017 Renovating Building Number - 18, Building Name - SCIENCE/MATH BLDG. (663 SS), (50439 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to</p>	\$4,539,510.00		

FLORIDA COLLEGE SYSTEM
PROJECT PRIORITY LIST REPORT
TALLAHASSEE COMMUNITY COLLEGE

Room 00212 (150 NSF), Room 00213 (154 NSF), Room 00214 (152 NSF), Room 00215 (155 NSF), Room 00216 (151 NSF), Room 00217 (155 NSF), Room 00218 (151 NSF), Room 00219 (155 NSF), Room 00220 (151 NSF), Room 00221 (155 NSF), Room 00222 (147 NSF), Room 00223 (152 NSF), Room 00224 (150 NSF), Room 00225 (155 NSF), Room 00226 (151 NSF), Room 00227 (155 NSF), Room 00228 (151 NSF), Room 00229 (155 NSF), Room 00230 (155 NSF), Room 00231 (155 NSF), Room 00232 (153 NSF), Room 00239 (148 NSF), Room 00240 (150 NSF), Room 00241 (151 NSF), Room 00242 (155 NSF), Room 00243 (153 NSF), Room 00244 (155 NSF), Room 00245 (189 NSF), Room 00246 (155 NSF), Room 00247 (520 NSF), Room 00249 (135 NSF), Room 00250 (312 NSF), Room 00250A (312 NSF), Room 00251 (94 NSF), Room 00252 (182 NSF), Room 00253 (124 NSF), Room 00254 (35 NSF), Room 00255 (186 NSF), Room 00256 (181 NSF), Room 00257 (178 NSF), Room 00258 (325 NSF), Room 00259 (129 NSF), Room 00260 (681 NSF), Room 00261 (134 NSF), Room 00262 (601 NSF), Room 00263 (189 NSF), Room 00264 (155 NSF), Room 00265 (153 NSF), Room 00266 (155 NSF), Room 00267 (151 NSF), Room 00268 (155 NSF), Room 00269 (148 NSF), Room 00270 (150 NSF), Room 00277 (153 NSF), Room 00278 (155 NSF), Room 00279 (155 NSF), Room 00280 (151 NSF), Room 00281 (155 NSF), Room 00282 (151 NSF), Room 00283 (155 NSF), Room 00284 (151 NSF), Room 00285 (155 NSF), Room 00286 (147 NSF), Room 00287 (153 NSF), Room 00288 (151 NSF), Room 00289 (155 NSF), Room 00290 (151 NSF), Room 00291 (155 NSF), Room 00292 (151 NSF), Room 00293 (155 NSF), Room 00294 (152 NSF), Room 00295 (155 NSF), Room 00296 (154 NSF), Room 00010X (1170 NSF), Room 00011X (1130 NSF), Room 00012X (1346 NSF), Room 00013X (1109 NSF), Room 00015X (1122 NSF), Room 00020X (1170 NSF), Room 00021X (1181 NSF), Room 00022X (191 NSF), Room 00100A (164 NSF), Room 00100B (180 NSF), Room 00100C (111 NSF), Room 00100D (111 NSF), Room 00100E (169 NSF), Room 00200 (241 NSF), Room 00200A (163 NSF), Room 00200B (180 NSF), Room 00200C (359 NSF), Room 00200D (169 NSF), Room 00200E (872 NSF), Room 00200F (613 NSF), Room 00200G (183 NSF), Room 00200H (198 NSF), Room 00200I (491 NSF), Room 00200J (860 NSF), Room 00209 (646 NSF), Room 00210 (656 NSF), Room 00211 (646 NSF), Room 00114 (1090 NSF), Room 00115 (231 NSF), Room 00116 (1090 NSF), Room 00117 (230 NSF), Room 00118 (658 NSF), Room 00119 (661 NSF), Room 00124 (688 NSF), Room 00125 (670 NSF), Room 00126 (640 NSF), Room 00128 (640 NSF), Room 00129 (670 NSF), Room 00130 (684 NSF), Room 00132 (660 NSF), Room 00133 (658 NSF), Room 00134 (654 NSF), Room 00135 (659 NSF), Room 00136 (658 NSF), Room 00137 (660 NSF), Room 00101 (1177 NSF), Room 00102 (542 NSF), Room 00103 (1177 NSF), Room 00104 (589 NSF), Room

FLORIDA COLLEGE SYSTEM
PROJECT PRIORITY LIST REPORT
TALLAHASSEE COMMUNITY COLLEGE

		00105 (1178 NSF), Room 00106 (589 NSF), Room 00201 (1212 NSF), Room 00205 (1212 NSF), Room 00207 (358 NSF), Room 00208 (1147 NSF), Room 00206 (214 NSF), Room 00202 (272 NSF), Room 00203 (367 NSF), Room 00204 (164 NSF)		
1	A	<p>Site: 1 MAIN CAMPUS Survey Recommendation: 1.018 Renovating Building Number - 15, Building Name - LIFETIME SPORTS CENT (68 SS), (53439 NSF) Apply Painting, Floor Cover, Electrical, Lighting, HVAC Systems, Bell/Fire Alarm Systems, Other to Room 00001X (1544 NSF), Room 00101 (1196 NSF), Room 00102 (1601 NSF), Room 00103 (165 NSF), Room 00104 (58 NSF), Room 00105 (145 NSF), Room 00106 (144 NSF), Room 00107A (83 NSF), Room 00108A (102 NSF), Room 00109 (440 NSF), Room 00110 (201 NSF), Room 00111 (625 NSF), Room 00112 (504 NSF), Room 00113 (406 NSF), Room 00113A (21 NSF), Room 00113B (21 NSF), Room 00114 (123 NSF), Room 00117 (38 NSF), Room 00118 (405 NSF), Room 00118A (18 NSF), Room 00118B (21 NSF), Room 00119 (123 NSF), Room 00122 (38 NSF), Room 00123 (131 NSF), Room 00124 (591 NSF), Room 00126 (1157 NSF), Room 00127 (433 NSF), Room 00127A (154 NSF), Room 00127B (137 NSF), Room 00128 (1584 NSF), Room 00129 (11695 NSF), Room 00130 (275 NSF), Room 00131 (275 NSF), Room 00132 (11625 NSF), Room 00133 (49 NSF), Room 00134 (117 NSF), Room 00135 (610 NSF), Room 00135A (54 NSF), Room 00137A (46 NSF), Room 00138 (42 NSF), Room 00139 (142 NSF), Room 00140 (156 NSF), Room 00141 (481 NSF), Room 00142 (49 NSF), Room 00143 (117 NSF), Room 00144 (627 NSF), Room 00144A (37 NSF), Room 00146A (44 NSF), Room 00151 (390 NSF), Room 00154 (23 NSF), Room 00157 (96 NSF), Room 00158 (75 NSF), Room 00162 (171 NSF), Room 00163 (75 NSF), Room 00164 (305 NSF), Room 00165 (34 NSF), Room 00166 (181 NSF), Room 00167 (50 NSF), Room 00168 (40 NSF), Room 00169 (181 NSF), Room 00170 (181 NSF), Room 00171 (50 NSF), Room 00173 (181 NSF), Room 00174 (292 NSF), Room 00176 (408 NSF), Room 00177 (174 NSF), Room 00178 (43 NSF), Room 00180 (181 NSF), Room 00181 (782 NSF), Room 00182 (3754 NSF), Room 00182A (110 NSF), Room 00183 (1973 NSF), Room 00200 (2360 NSF), Room 00160 (983 NSF), Room 00161 (847 NSF), Room 00159 (849 NSF)</p>	\$4,809,510.00	

FLORIDA COLLEGE SYSTEM
PROJECT PRIORITY LIST REPORT
TALLAHASSEE COMMUNITY COLLEGE

Project Number	Priority Ranking	Description	Estimated Cost	Status	Completed Date
1	A	Site: 1 MAIN CAMPUS Survey Recommendation: 1.019 Renovating Building Number - 12, Building Name - FINE AND PERFORMING (50 SS), (51496 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 00131 (1202 NSF), Room 00132 (1194 NSF), Room 00134 (568 NSF), Room 00135 (224 NSF), Room 00135B (87 NSF), Room 00136 (69 NSF), Room 00136A (82 NSF), Room 00138 (551 NSF), Room 00139 (290 NSF), Room 00140 (5167 NSF), Room 00141 (383 NSF), Room 00142 (24 NSF), Room 00143 (367 NSF), Room 00144 (977 NSF), Room 00145 (248 NSF), Room 00145A (286 NSF), Room 00146 (1343 NSF), Room 00147 (1309 NSF), Room 00148 (82 NSF), Room 00149 (57 NSF), Room 00149A (272 NSF), Room 00150 (82 NSF), Room 00151 (302 NSF), Room 00152 (344 NSF), Room 00155 (285 NSF), Room 00156 (169 NSF), Room 00157 (290 NSF), Room 00158 (24 NSF), Room 00159 (551 NSF), Room 00161 (800 NSF), Room 00202 (1688 NSF), Room 00203 (342 NSF), Room 00204 (243 NSF), Room 00206 (324 NSF), Room 00206A (52 NSF), Room 00207 (1445 NSF), Room 00209A (97 NSF), Room 00210 (333 NSF), Room 00211 (712 NSF), Room 00211A (170 NSF), Room 00215 (634 NSF), Room 00216 (712 NSF), Room 00217 (752 NSF), Room 00217A (359 NSF), Room 00217B (178 NSF), Room 00218A (711 NSF), Room 00218B (356 NSF), Room 00219 (218 NSF), Room 00220 (51 NSF), Room 00222 (172 NSF), Room 00223 (760 NSF), Room 00224 (241 NSF), Room 00225 (206 NSF), Room 00226 (109 NSF), Room 00227 (24 NSF), Room 00228 (107 NSF), Room 00229 (107 NSF), Room 00230 (162 NSF), Room 00231 (229 NSF), Room 00232 (104 NSF), Room 00233 (104 NSF), Room 00234 (426 NSF), Room 00237 (87 NSF), Room 00238 (229 NSF), Room 00239 (65 NSF), Room 00241 (529 NSF), Room 00242 (519 NSF), Room 00244 (922 NSF), Room 00301 (1983 NSF), Room 00109 (790 NSF), Room 00110 (130 NSF), Room 00111 (407 NSF), Room 00112 (668 NSF), Room 00113 (888 NSF), Room 00115 (797 NSF), Room 00116 (298 NSF), Room 00100 (656 NSF), Room 00100A (1942 NSF), Room 00101 (169 NSF), Room 00102 (950 NSF), Room 00103 (1956 NSF), Room 00104 (1312 NSF), Room 00128 (127 NSF), Room 00126 (123 NSF), Room 00104A (175 NSF), Room 00119 (179 NSF), Room 00119A (132 NSF), Room 00120 (81 NSF), Room 00120A (122 NSF), Room 00121 (751 NSF), Room 00125 (780 NSF), Room 00127 (822 NSF), Room 00129 (824 NSF), Room 00130 (121 NSF), Room 00208 (1440 NSF), Room 00209 (765 NSF)	\$4,634,640.00		

FLORIDA COLLEGE SYSTEM
PROJECT PRIORITY LIST REPORT
TALLAHASSEE COMMUNITY COLLEGE

1	A	<p>Site: 1 MAIN CAMPUS Survey Recommendation: 1.020 Renovating Building Number - 11, Building Name - TECHNOLOGY & PROFESS (676 SS), (69617 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 00132 (257 NSF), Room 00133 (224 NSF), Room 00134A (122 NSF), Room 00134B (120 NSF), Room 00135 (223 NSF), Room 00136 (109 NSF), Room 00137 (109 NSF), Room 00138 (109 NSF), Room 00139 (114 NSF), Room 00140 (349 NSF), Room 00141 (507 NSF), Room 00142 (318 NSF), Room 00143 (111 NSF), Room 00144 (115 NSF), Room 00145 (106 NSF), Room 00146 (114 NSF), Room 00147 (121 NSF), Room 00148 (108 NSF), Room 00151 (265 NSF), Room 00151A (61 NSF), Room 00152 (111 NSF), Room 00153 (111 NSF), Room 00154 (111 NSF), Room 00155 (116 NSF), Room 00158 (301 NSF), Room 00159 (185 NSF), Room 00159A (130 NSF), Room 00160 (441 NSF), Room 00160A (54 NSF), Room 00161 (149 NSF), Room 00162 (18 NSF), Room 00163 (18 NSF), Room 00164 (162 NSF), Room 00165 (223 NSF), Room 00166 (198 NSF), Room 00168 (110 NSF), Room 00169 (315 NSF), Room 00001X (1154 NSF), Room 00002X (1091 NSF), Room 00003X (2060 NSF), Room 00004X (171 NSF), Room 00005X (171 NSF), Room 00100 (288 NSF), Room 00100A (85 NSF), Room 00101 (214 NSF), Room 00105 (611 NSF), Room 00108 (207 NSF), Room 00122 (1017 NSF), Room 00123 (65 NSF), Room 00171 (64 NSF), Room 00172 (126 NSF), Room 00173 (91 NSF), Room 00174 (66 NSF), Room 00175 (92 NSF), Room 00126A (52 NSF), Room 00127 (465 NSF), Room 00128 (299 NSF), Room 00179 (247 NSF), Room 00180 (62 NSF), Room 00181 (91 NSF), Room 00223 (1125 NSF), Room 00225 (215 NSF), Room 00226 (415 NSF), Room 00227 (12 NSF), Room 00228 (139 NSF), Room 00229 (116 NSF), Room 00230 (119 NSF), Room 00231 (114 NSF), Room 00232 (246 NSF), Room 00233 (569 NSF), Room 00234 (228 NSF), Room 00235 (136 NSF), Room 00236 (152 NSF), Room 00237 (140 NSF), Room 00238 (477 NSF), Room 00239 (253 NSF), Room 00240 (109 NSF), Room 00241 (111 NSF), Room 00242 (109 NSF), Room 00243 (105 NSF), Room 00244 (110 NSF), Room 00245 (98 NSF), Room 00246 (115 NSF), Room 00247 (109 NSF), Room 00248 (116 NSF), Room 00249 (129 NSF), Room 00250 (108 NSF), Room 00251 (130 NSF), Room 00252 (16 NSF), Room 00253 (198 NSF), Room 00254 (114 NSF), Room 00255 (106 NSF), Room 00256 (111 NSF), Room 00257 (111 NSF), Room 00258 (111 NSF), Room 00259 (288 NSF), Room 00260A (61 NSF), Room 00262 (225 NSF), Room 00265 (250 NSF), Room 00266 (234 NSF), Room 00267 (23 NSF), Room 00268 (1460 NSF), Room 00269 (93 NSF), Room 00269A (173 NSF), Room 00270 (163 NSF), Room 00270A (201 NSF), Room 00276 (228 NSF), Room</p>	\$6,265,530.00		
---	---	--	----------------	--	--

FLORIDA COLLEGE SYSTEM
PROJECT PRIORITY LIST REPORT
TALLAHASSEE COMMUNITY COLLEGE

00282 (350 NSF), Room 00282A (222 NSF), Room 00283 (22 NSF), Room 00284 (108 NSF), Room 00285 (112 NSF), Room 00286 (133 NSF), Room 00287 (120 NSF), Room 00288 (127 NSF), Room 00289 (104 NSF), Room 00290 (105 NSF), Room 00291 (135 NSF), Room 00292 (102 NSF), Room 00293 (96 NSF), Room 00294 (114 NSF), Room 00295 (114 NSF), Room 00296 (114 NSF), Room 00297 (197 NSF), Room 00298 (179 NSF), Room 00299 (226 NSF), Room 00299A (144 NSF), Room 00299B (108 NSF), Room 00299C (106 NSF), Room 00299D (106 NSF), Room 00299E (106 NSF), Room 00299F (105 NSF), Room 00299G (238 NSF), Room 00299H (153 NSF), Room 00299I (155 NSF), Room 00299J (207 NSF), Room 00299K (196 NSF), Room 00299L (151 NSF), Room 00299M (160 NSF), Room 00299N (148 NSF), Room 00299O (113 NSF), Room 00299P (146 NSF), Room 00299Q (159 NSF), Room 00299R (159 NSF), Room 00300 (26 NSF), Room 00314 (243 NSF), Room 00316 (225 NSF), Room 00318 (715 NSF), Room 00318A (94 NSF), Room 00323 (716 NSF), Room 00324 (181 NSF), Room 00325 (2741 NSF), Room 00400 (2957 NSF), Room 00197 (227 NSF), Room 00198 (231 NSF), Room 00199 (2626 NSF), Room 00200 (695 NSF), Room 00200A (85 NSF), Room 00201 (214 NSF), Room 00183 (26 NSF), Room 00209 (90 NSF), Room 00189 (95 NSF), Room 00279 (127 NSF), Room 00280 (132 NSF), Room 00281 (753 NSF), Room 00220 (64 NSF), Room 00221 (1166 NSF), Room 00218 (1363 NSF), Room 00210 (1067 NSF), Room 00211 (1156 NSF), Room 00212 (132 NSF), Room 00204 (829 NSF), Room 00205 (854 NSF), Room 00206 (1018 NSF), Room 00207 (1253 NSF), Room 00208 (123 NSF), Room 00278 (837 NSF), Room 00130 (814 NSF), Room 00176 (310 NSF), Room 00177 (172 NSF), Room 00119 (1015 NSF), Room 00170 (1457 NSF), Room 00104 (1155 NSF), Room 00190 (175 NSF), Room 00126 (68 NSF), Room 00186 (473 NSF), Room 00186A (316 NSF), Room 00188 (919 NSF), Room 00124 (733 NSF), Room 00219 (82 NSF), Room 00222 (128 NSF), Room 00178 (891 NSF), Room 00182 (918 NSF), Room 00111 (1155 NSF), Room 00112 (1015 NSF), Room 00114 (1015 NSF), Room 00116 (1015 NSF), Room 00213 (76 NSF), Room 00214 (143 NSF), Room 00184 (851 NSF), Room 00118 (115 NSF), Room 00120 (115 NSF), Room 00121 (1015 NSF)

FLORIDA COLLEGE SYSTEM
PROJECT PRIORITY LIST REPORT
TALLAHASSEE COMMUNITY COLLEGE

Project Number: 1		No Comments Provided			
Project Number	Priority Ranking	Description	Estimated Cost	Status	Completed Date
1	A	Site: 1 MAIN CAMPUS Survey Recommendation: 1.021 Renovating Building Number - 8, Building Name - ACADEMIC COMPUTING C (645 SS), (37472 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 00001X (1042 NSF), Room 00002X (545 NSF), Room 00003X (102 NSF), Room 00004X (299 NSF), Room 00005X (367 NSF), Room 00100A (153 NSF), Room 00100B (156 NSF), Room 00100C (157 NSF), Room 00100D (266 NSF), Room 00104 (210 NSF), Room 00105 (417 NSF), Room 00110 (126 NSF), Room 00111 (111 NSF), Room 00115 (386 NSF), Room 00122 (178 NSF), Room 00123 (387 NSF), Room 00124 (228 NSF), Room 00125 (191 NSF), Room 00126 (96 NSF), Room 00127 (651 NSF), Room 00128 (96 NSF), Room 00129 (92 NSF), Room 00130 (243 NSF), Room 00133 (1563 NSF), Room 00135 (100 NSF), Room 00136 (100 NSF), Room 00137 (296 NSF), Room 00200A (160 NSF), Room 00200B (160 NSF), Room 00200C (157 NSF), Room 00200D (246 NSF), Room 00204 (188 NSF), Room 00205 (203 NSF), Room 00209 (267 NSF), Room 00210 (3520 NSF), Room 00300A (159 NSF), Room 00300B (157 NSF), Room 00300C (157 NSF), Room 00300D (282 NSF), Room 00304 (190 NSF), Room 00305 (178 NSF), Room 00309 (98 NSF), Room 00309A (89 NSF), Room 00310 (250 NSF), Room 00310A (115 NSF), Room 00311 (99 NSF), Room 00313 (93 NSF), Room 00314 (192 NSF), Room 00315 (96 NSF), Room 00316 (255 NSF), Room 00317 (280 NSF), Room 00318 (99 NSF), Room 00319 (160 NSF), Room 00321 (365 NSF), Room 00322 (656 NSF), Room 00218 (273 NSF), Room 00325 (681 NSF), Room 00326 (267 NSF), Room 00329 (284 NSF), Room 00213 (305 NSF), Room 00333 (202 NSF), Room 00335 (658 NSF), Room 00214 (125 NSF), Room 00215 (115 NSF), Room 00330 (1197 NSF), Room 00331 (1220 NSF), Room 00332 (1149 NSF), Room 00332A (33 NSF), Room 00219 (1265 NSF), Room 00220 (1332 NSF), Room 00221 (1147 NSF), Room 00222 (44 NSF), Room 00323 (1170 NSF), Room 00324 (1108 NSF), Room 00211 (1185 NSF), Room 00212 (1304 NSF), Room 00117 (98 NSF), Room 00118 (600 NSF), Room 00119 (1225 NSF), Room 00112 (1106 NSF), Room 00113 (65 NSF), Room 00114 (85 NSF), Room 00109 (1118 NSF), Room 00134 (682 NSF)	\$3,372,480.00		

FLORIDA COLLEGE SYSTEM
PROJECT PRIORITY LIST REPORT
TALLAHASSEE COMMUNITY COLLEGE

Project Number: 1		No Comments Provided			
Project Number	Priority Ranking	Description	Estimated Cost	Status	Completed Date
1	A	Site: 1 MAIN CAMPUS Survey Recommendation: 1.022 Renovating Building Number - 6, Building Name - DENTAL HYGIENE BLDG. (499 SS), (33280 NSF) Apply Painting, Floor Cover, Lighting, HVAC Systems to Room00226 (285 NSF), Room 00227 (561 NSF), Room 00228 (1130 NSF), Room 00300 (1880 NSF), Room 00001 (370 NSF), Room 00001X (3539 NSF), Room 00002X (313 NSF), Room 00003X (54 NSF), Room 00004X (56 NSF), Room 00100 (319 NSF), Room 00100A (148 NSF), Room 00221A (357 NSF), Room 00221B (207 NSF), Room 00103 (120 NSF), Room 00105 (106 NSF), Room 00118 (135 NSF), Room 00121 (120 NSF), Room 00122 (248 NSF), Room 00123 (224 NSF), Room 00124 (214 NSF), Room 00125 (89 NSF), Room 00126 (184 NSF), Room 00127 (90 NSF), Room 00128 (141 NSF), Room 00129 (59 NSF), Room 00130 (93 NSF), Room 00132 (157 NSF), Room 00133 (81 NSF), Room 00133A (106 NSF), Room 00133B (38 NSF), Room 002101 (95 NSF), Room 002102 (105 NSF), Room 002103 (100 NSF), Room 002104 (111 NSF), Room 002105 (115 NSF), Room 002106 (100 NSF), Room 002107 (104 NSF), Room 00210A (45 NSF), Room 00210B (194 NSF), Room 00210C (83 NSF), Room 00210D (37 NSF), Room 00210E (128 NSF), Room 00213 (192 NSF), Room 00109 (183 NSF), Room 00107 (83 NSF), Room 00137 (317 NSF), Room 00201 (1218 NSF), Room 00139 (97 NSF), Room 00140 (160 NSF), Room 00141 (1060 NSF), Room 00204 (1124 NSF), Room 00205 (891 NSF), Room 00205A (293 NSF), Room 00206 (1093 NSF), Room 00207 (915 NSF), Room 00209 (948 NSF), Room 00217 (161 NSF), Room 00218 (887 NSF), Room 00219 (880 NSF), Room 00225 (952 NSF), Room 00220 (1193 NSF), Room 00221 (1335 NSF), Room 00106 (154 NSF), Room 00104 (181 NSF), Room 00100B (233 NSF), Room 00101 (2327 NSF), Room 00102 (218 NSF), Room 00135 (1248 NSF), Room 00136 (1062 NSF), Room 00138 (160 NSF), Room 00108 (87 NSF), Room 00110 (190 NSF), Room 00114 (252 NSF), Room 00115 (211 NSF), Room 00116 (174 NSF), Room 00117 (160 NSF)	\$2,995,200.00		
1	A	Site: 1 MAIN CAMPUS Survey Recommendation: 1.023 Renovating Building Number - 5, Building Name - COMMUNICATIONS AND H (659 SS), (55793 NSF) Apply Painting, Floor Cover, Plumbing, Windows, Lighting, HVAC	\$5,021,370.00		

FLORIDA COLLEGE SYSTEM
PROJECT PRIORITY LIST REPORT
TALLAHASSEE COMMUNITY COLLEGE

Systems, Bell/Fire Alarm Systems, Retrofit for Technology to Room00265 (1148 NSF), Room 00266 (137 NSF), Room 00269 (319 NSF), Room 00270 (210 NSF), Room 00276 (92 NSF), Room 00277 (89 NSF), Room 00278 (112 NSF), Room 00279 (112 NSF), Room 00280 (91 NSF), Room 00281 (91 NSF), Room 00282 (111 NSF), Room 00284 (69 NSF), Room 00285 (69 NSF), Room 00286 (209 NSF), Room 00288 (233 NSF), Room 00289 (35 NSF), Room 00295 (137 NSF), Room 00300 (12890 NSF), Room 00100 (156 NSF), Room 00102 (919 NSF), Room 00103 (44 NSF), Room 00105 (131 NSF), Room 00106 (130 NSF), Room 00109 (131 NSF), Room 00110 (129 NSF), Room 00112 (44 NSF), Room 00113 (130 NSF), Room 00114 (181 NSF), Room 00115 (41 NSF), Room 00117 (133 NSF), Room 00118 (134 NSF), Room 00121 (133 NSF), Room 00122 (40 NSF), Room 00123 (126 NSF), Room 00128 (24 NSF), Room 00129 (28 NSF), Room 00258 (169 NSF), Room 00259B (445 NSF), Room 00261 (141 NSF), Room 00262 (125 NSF), Room 00131 (114 NSF), Room 00132 (144 NSF), Room 00133 (78 NSF), Room 00134 (78 NSF), Room 00136 (61 NSF), Room 00140 (307 NSF), Room 00140A (88 NSF), Room 00144 (353 NSF), Room 00169 (342 NSF), Room 00170 (1271 NSF), Room 00171 (54 NSF), Room 00172 (59 NSF), Room 00173 (56 NSF), Room 00174 (59 NSF), Room 00175 (56 NSF), Room 00178 (32 NSF), Room 00179 (44 NSF), Room 00180 (215 NSF), Room 00181 (120 NSF), Room 00182 (122 NSF), Room 00183 (122 NSF), Room 00184 (120 NSF), Room 00200 (1139 NSF), Room 00201 (51 NSF), Room 00202 (127 NSF), Room 00204 (131 NSF), Room 00206 (133 NSF), Room 00207 (175 NSF), Room 00208 (163 NSF), Room 00209 (139 NSF), Room 00210 (327 NSF), Room 00213 (21 NSF), Room 00216 (51 NSF), Room 00216A (138 NSF), Room 00221 (450 NSF), Room 00222 (51 NSF), Room 00224 (131 NSF), Room 00225 (132 NSF), Room 00146 (866 NSF), Room 00147 (414 NSF), Room 00155 (134 NSF), Room 00166 (123 NSF), Room 00167 (326 NSF), Room 00231 (157 NSF), Room 00243 (1594 NSF), Room 00244 (1031 NSF), Room 00247 (137 NSF), Room 00248 (81 NSF), Room 00249 (44 NSF), Room 00228 (529 NSF), Room 00251 (91 NSF), Room 00255 (61 NSF), Room 00256 (61 NSF), Room 00257 (149 NSF), Room 00230 (692 NSF), Room 00233 (690 NSF), Room 00234 (694 NSF), Room 00235 (683 NSF), Room 00236 (696 NSF), Room 00165A (42 NSF), Room 00165B (42 NSF), Room 00156 (922 NSF), Room 00157 (922 NSF), Room 00158 (1179 NSF), Room 00159 (455 NSF), Room 00160 (1242 NSF), Room 00161 (1174 NSF), Room 00162 (121 NSF), Room 00227 (860 NSF), Room 00263 (692 NSF), Room 00264 (707 NSF), Room 00130 (764 NSF), Room 00168 (315 NSF), Room 00165 (1536 NSF), Room 00254 (1189 NSF), Room 00250 (373 NSF), Room 00245 (946 NSF), Room 00246 (207 NSF), Room 00260 (1227 NSF), Room 00259 (1272 NSF), Room 00145 (856 NSF), Room 00141 (850 NSF), Room

FLORIDA COLLEGE SYSTEM
PROJECT PRIORITY LIST REPORT
TALLAHASSEE COMMUNITY COLLEGE

		00137 (415 NSF), Room 00163 (117 NSF), Room 00164 (203 NSF), Room 00139 (970 NSF)			
1	A	<p>Site: 1 MAIN CAMPUS Survey Recommendation: 1.024 Renovating Building Number - 3, Building Name - ACADEMIC SPT BLDG. (38 SS), (12954 NSF) Apply Painting, Floor Cover, Lighting, Retrofit for Technology, Other to Room 00150 (134 NSF), Room 00150A (11 NSF), Room 00150B (41 NSF), Room 00151 (137 NSF), Room 00154 (146 NSF), Room 00155 (146 NSF), Room 00156 (146 NSF), Room 00157 (146 NSF), Room 00158 (163 NSF), Room 00159 (163 NSF), Room 00160 (430 NSF), Room 00250 (200 NSF), Room 00251 (293 NSF), Room 00258 (489 NSF), Room 00259 (129 NSF), Room 00260 (127 NSF), Room 00261 (161 NSF), Room 00262 (13 NSF), Room 00263 (471 NSF), Room 00265 (106 NSF), Room 00266 (107 NSF), Room 00267 (106 NSF), Room 00268 (104 NSF), Room 00269 (105 NSF), Room 00271 (106 NSF), Room 00272 (106 NSF), Room 00273 (108 NSF), Room 00274 (75 NSF), Room 00275 (146 NSF), Room 00276 (250 NSF), Room 00277 (426 NSF), Room 00278 (125 NSF), Room 00278A (132 NSF), Room 00279 (196 NSF), Room 00279A (78 NSF), Room 00280 (62 NSF), Room 00281 (185 NSF), Room 00282 (209 NSF), Room 00283 (187 NSF), Room 00284 (131 NSF), Room 00285 (101 NSF), Room 00288 (90 NSF), Room 00289 (424 NSF), Room 00290 (144 NSF), Room 00291 (150 NSF), Room 00292 (150 NSF), Room 00293 (158 NSF), Room 00294A (83 NSF), Room 00294B (88 NSF), Room 00295 (180 NSF), Room 00296 (110 NSF), Room 00001A (192 NSF), Room 00001B (177 NSF), Room 00001X (1368 NSF), Room 00002X (605 NSF), Room 00003X (1381 NSF), Room 00149 (957 NSF)</p>	\$1,165,860.00		
1	A	<p>Site: 1 MAIN CAMPUS Survey Recommendation: 1.025 Renovating Building Number - 4, Building Name - MOORE LECTURE HALL (161 SS), (5197 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 00153 (190 NSF), Room 00154 (174 NSF), Room 00155 (174 NSF), Room 00156 (190 NSF), Room 00157 (31 NSF), Room 00158 (31 NSF), Room 00151 (2014 NSF), Room 00151A (293 NSF), Room 00151B (88 NSF), Room 00152 (2012 NSF)</p>	\$467,730.00		

FLORIDA COLLEGE SYSTEM
PROJECT PRIORITY LIST REPORT
TALLAHASSEE COMMUNITY COLLEGE

Project Number: 1		No Comments Provided			
Project Number	Priority Ranking	Description	Estimated Cost	Status	Completed Date
1	A	Site: 1 MAIN CAMPUS Survey Recommendation: 1.026 Renovating Building Number - 2, Building Name - SCIENCE/MATH ANNEX (74 SS), (21947 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 00001A (124 NSF), Room 00001B (244 NSF), Room 00001C (108 NSF), Room 00001X (695 NSF), Room 00002A (178 NSF), Room 00002B (213 NSF), Room 00002C (84 NSF), Room 00002X (865 NSF), Room 00006X (1032 NSF), Room 00007X (169 NSF), Room 000C2 (101 NSF), Room 00100 (513 NSF), Room 00101 (204 NSF), Room 00101A (77 NSF), Room 00101B (80 NSF), Room 00101C (205 NSF), Room 00102 (389 NSF), Room 00102A (64 NSF), Room 00103 (288 NSF), Room 00208 (383 NSF), Room 00209 (83 NSF), Room 00210 (178 NSF), Room 00210A (102 NSF), Room 00210B (102 NSF), Room 00210C (102 NSF), Room 00210D (102 NSF), Room 00211 (143 NSF), Room 00212 (142 NSF), Room 00213 (142 NSF), Room 00214 (143 NSF), Room 00215 (143 NSF), Room 00216 (142 NSF), Room 00217 (146 NSF), Room 00218 (153 NSF), Room 00220 (153 NSF), Room 00221 (154 NSF), Room 00222 (186 NSF), Room 00223 (136 NSF), Room 00224 (136 NSF), Room 00225 (136 NSF), Room 00226 (133 NSF), Room 00227 (9 NSF), Room 00230 (274 NSF), Room 00231 (242 NSF), Room 00236 (305 NSF), Room 00238 (253 NSF), Room 00241 (183 NSF), Room 00300 (8907 NSF), Room 00140 (1539 NSF), Room 00140A (211 NSF), Room 00237 (295 NSF), Room 00242 (180 NSF), Room 00239 (525 NSF), Room 00240 (151 NSF)	\$1,975,230.00		

FLORIDA COLLEGE SYSTEM
PROJECT PRIORITY LIST REPORT
TALLAHASSEE COMMUNITY COLLEGE

1	A	<p>Site: 1 MAIN CAMPUS Survey Recommendation: 1.027 Renovating Building Number - 1, Building Name - ENGLISH BLDG (537 SS), (34920 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 00001A (209 NSF), Room 00001B (106 NSF), Room 00001C (108 NSF), Room 00001X (598 NSF), Room 00002B (199 NSF), Room 00002X (4342 NSF), Room 00003X (185 NSF), Room 00100 (176 NSF), Room 00101 (492 NSF), Room 00102 (597 NSF), Room 00108 (42 NSF), Room 00109 (77 NSF), Room 00111 (180 NSF), Room 00200 (129 NSF), Room 00208 (487 NSF), Room 00210 (112 NSF), Room 00211 (202 NSF), Room 00212 (110 NSF), Room 00213 (201 NSF), Room 00214 (120 NSF), Room 00215 (120 NSF), Room 00216 (119 NSF), Room 00217 (119 NSF), Room 00218 (120 NSF), Room 00219 (121 NSF), Room 00220 (118 NSF), Room 00221 (117 NSF), Room 00222 (130 NSF), Room 00223 (69 NSF), Room 00223A (51 NSF), Room 00223B (51 NSF), Room 00223C (54 NSF), Room 00223D (54 NSF), Room 00224 (80 NSF), Room 00225 (446 NSF), Room 00226 (446 NSF), Room 00227 (876 NSF), Room 00117 (280 NSF), Room 00118 (155 NSF), Room 00119 (121 NSF), Room 00121A (80 NSF), Room 00121B (124 NSF), Room 00125 (427 NSF), Room 00232 (428 NSF), Room 00248 (245 NSF), Room 00248A (98 NSF), Room 00249 (692 NSF), Room 00252 (190 NSF), Room 00254 (141 NSF), Room 00255 (137 NSF), Room 00257 (15 NSF), Room 00258 (232 NSF), Room 00258A (16 NSF), Room 00259 (135 NSF), Room 00260 (150 NSF), Room 00261 (136 NSF), Room 00262 (135 NSF), Room 00263 (134 NSF), Room 00264 (96 NSF), Room 00265 (429 NSF), Room 00267 (236 NSF), Room 00267A (20 NSF), Room 00268 (159 NSF), Room 00269 (56 NSF), Room 00270 (168 NSF), Room 00272 (205 NSF), Room 00273 (208 NSF), Room 00274 (308 NSF), Room 00275 (56 NSF), Room 00276 (75 NSF), Room 00240 (479 NSF), Room 00241 (430 NSF), Room 00242 (16 NSF), Room 00243 (352 NSF), Room 00244 (330 NSF), Room 00245 (210 NSF), Room 00246 (12 NSF), Room 00128 (591 NSF), Room 00129 (413 NSF), Room 00132 (324 NSF), Room 00134 (253 NSF), Room 00135 (961 NSF), Room 00247 (1099 NSF), Room 00233 (853 NSF), Room 00234 (850 NSF), Room 00235 (837 NSF), Room 00236 (77 NSF), Room 00237 (847 NSF), Room 00238 (81 NSF), Room 00239 (1030 NSF), Room 00126 (674 NSF), Room 00127 (643 NSF), Room 00120 (684 NSF), Room 00121 (676 NSF), Room 00231 (61 NSF), Room 00112 (815 NSF), Room 00113 (700 NSF), Room 00114 (928 NSF), Room 00115 (1026 NSF), Room 00116 (818 NSF) Renovation Description: TOTAL BUILDING RENOVATION</p>	\$3,142,800.00		
---	---	---	----------------	--	--

FLORIDA COLLEGE SYSTEM
PROJECT PRIORITY LIST REPORT
TALLAHASSEE COMMUNITY COLLEGE

Project Number: 1		No Comments Provided			
Project Number	Priority Ranking	Description	Estimated Cost	Status	Completed Date
1	A	Site: 3 FLORIDA PUBLIC SAFET Survey Recommendation: 3.014 Renovating Building Number - 8, Building Name - DINING FACILITY (0 SS), (11327 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room00100 (299 NSF), Room 00101 (82 NSF), Room 00102 (1335 NSF), Room 00103 (502 NSF), Room 00104 (101 NSF), Room 00104A (108 NSF), Room 00104B (96 NSF), Room 00104C (83 NSF), Room 00105 (703 NSF), Room 00108 (75 NSF), Room 00110 (78 NSF), Room 00111 (111 NSF), Room 00112 (247 NSF), Room 00113 (46 NSF), Room 00118 (138 NSF), Room 00121 (6432 NSF), Room 00123 (64 NSF), Room 00124 (260 NSF), Room 00125 (122 NSF), Room 00126 (355 NSF), Room 00801 (90 NSF)	\$1,019,430.00		
1	A	Site: 3 FLORIDA PUBLIC SAFET Survey Recommendation: 3.015 Renovating Building Number - 16, Building Name - CONFERENCE CENTER BU (0 SS), (9316 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 00100 (378 NSF), Room 00100A (1515 NSF), Room 00100B (1655 NSF), Room 00100C (1517 NSF), Room 00101 (1584 NSF), Room 00102 (84 NSF), Room 00103 (246 NSF), Room 00104 (256 NSF), Room 00105 (103 NSF), Room 00107 (122 NSF), Room 00111 (128 NSF), Room 00112 (367 NSF), Room 00113 (407 NSF), Room 00114 (588 NSF), Room 00115 (53 NSF), Room 00118 (260 NSF), Room 00120 (53 NSF)	\$838,440.00		

FLORIDA COLLEGE SYSTEM
PROJECT PRIORITY LIST REPORT
TALLAHASSEE COMMUNITY COLLEGE

Project Number: 1		No Comments Provided			
Project Number	Priority Ranking	Description	Estimated Cost	Status	Completed Date
1	A	Site: 3 FLORIDA PUBLIC SAFET Survey Recommendation: 3.016 Renovating Building Number - 10, Building Name - DORM WING (SOUTH) (0 SS), (5256 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 00001B (254 NSF), Room 00002B (254 NSF), Room 00003B (254 NSF), Room 00004B (254 NSF), Room 00005B (254 NSF), Room 00006B (254 NSF), Room 00007B (254 NSF), Room 00008B (254 NSF), Room 00009B (254 NSF), Room 00010B (254 NSF), Room 00011B (254 NSF), Room 00012B (254 NSF), Room 00013B (254 NSF), Room 00014B (254 NSF), Room 00015B (254 NSF), Room 00016B (254 NSF), Room 00017 (80 NSF), Room 00018 (80 NSF), Room 00019 (80 NSF), Room 00020 (80 NSF), Room 00021 (80 NSF), Room 00022 (80 NSF), Room 00023 (80 NSF), Room 00024 (80 NSF), Room 00800 (552 NSF)	\$473,040.00		
1	A	Site: 3 FLORIDA PUBLIC SAFET Survey Recommendation: 3.017 Renovating Building Number - 4, Building Name - ADMINISTRATION BUILD (0 SS), (25901 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 00101 (740 NSF), Room 00101X (406 NSF), Room 00102 (352 NSF), Room 00103 (466 NSF), Room 00104 (351 NSF), Room 00105 (350 NSF), Room 00106 (119 NSF), Room 00107 (350 NSF), Room 00110 (2172 NSF), Room 00111 (74 NSF), Room 00114 (68 NSF), Room 00116 (292 NSF), Room 00117 (303 NSF), Room 00118 (204 NSF), Room 00119 (250 NSF), Room 00120 (138 NSF), Room 00121 (558 NSF), Room 00122 (801 NSF), Room 00123 (104 NSF), Room 00124 (419 NSF), Room 00125 (638 NSF), Room 00126 (189 NSF), Room 00127 (184 NSF), Room 00128 (240 NSF), Room 00129 (126 NSF), Room 00130 (126 NSF), Room 00131 (258 NSF), Room 00132 (140 NSF), Room 00133 (208 NSF), Room 00134 (148 NSF), Room 00135 (164 NSF), Room 00136 (140 NSF), Room 00137 (182 NSF), Room 00138 (130 NSF), Room 00139 (118 NSF), Room 00140 (177 NSF), Room 00141 (174 NSF), Room 00142 (192 NSF), Room 00143 (20 NSF), Room 00144 (108 NSF), Room 00145 (104 NSF), Room 00146 (165 NSF), Room 00147 (112 NSF), Room 00148 (112 NSF), Room 00149 (112 NSF), Room 00150	\$2,331,090.00		

FLORIDA COLLEGE SYSTEM
PROJECT PRIORITY LIST REPORT
TALLAHASSEE COMMUNITY COLLEGE

(114 NSF), Room 00151 (20 NSF), Room 00152 (106 NSF), Room 00153 (110 NSF), Room 00201 (1571 NSF), Room 00202 (690 NSF), Room 00203 (550 NSF), Room 00204 (199 NSF), Room 00205 (128 NSF), Room 00206 (119 NSF), Room 00210 (78 NSF), Room 00213 (272 NSF), Room 00214 (383 NSF), Room 00215 (64 NSF), Room 00216 (70 NSF), Room 00217 (211 NSF), Room 00218 (555 NSF), Room 00219 (541 NSF), Room 00220 (555 NSF), Room 00221 (527 NSF), Room 00222 (165 NSF), Room 00223 (249 NSF), Room 00224 (115 NSF), Room 00225 (210 NSF), Room 00226 (184 NSF), Room 00227 (121 NSF), Room 00228 (115 NSF), Room 00229 (28 NSF), Room 00230 (121 NSF), Room 00231 (106 NSF), Room 00232 (101 NSF), Room 00233 (104 NSF), Room 00234 (168 NSF), Room 00235 (157 NSF), Room 00236 (120 NSF), Room 00237 (116 NSF), Room 00238 (114 NSF), Room 00239 (114 NSF), Room 00240 (183 NSF), Room 00241 (138 NSF), Room 00242 (114 NSF), Room 00243 (114 NSF), Room 00244 (116 NSF), Room 00245 (188 NSF), Room 00246 (114 NSF), Room 00247 (173 NSF), Room 00248 (116 NSF), Room 00249 (116 NSF), Room 00250 (116 NSF), Room 00251 (202 NSF), Room 00252 (144 NSF), Room 00254 (108 NSF), Room 00255 (105 NSF), Room 00256 (20 NSF), Room 00257 (118 NSF), Room 00258 (116 NSF), Room 00259 (118 NSF), Room 00260 (20 NSF), Room 00261 (104 NSF), Room 00262 (100 NSF), Room 00263 (180 NSF), Room 00264 (64 NSF), Room 00265 (116 NSF), Room 00266 (120 NSF), Room 00293 (23 NSF), Room 00294 (350 NSF), Room 00295 (350 NSF)			
---	--	--	--

FLORIDA COLLEGE SYSTEM
PROJECT PRIORITY LIST REPORT
TALLAHASSEE COMMUNITY COLLEGE

Project Number: 1		No Comments Provided			
Project Number	Priority Ranking	Description	Estimated Cost	Status	Completed Date
1	A	Site: 3 FLORIDA PUBLIC SAFET Survey Recommendation: 3.018 Renovating Building Number - 3, Building Name - CLASSROOM BUILDING A (589 SS), (29846 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 00100 (43 NSF), Room 00101 (2435 NSF), Room 00102 (105 NSF), Room 00103 (203 NSF), Room 00104 (204 NSF), Room 00105 (1375 NSF), Room 00105A (113 NSF), Room 00122 (121 NSF), Room 00123 (120 NSF), Room 00124 (76 NSF), Room 00125 (100 NSF), Room 00200 (211 NSF), Room 00201 (1018 NSF), Room 00202 (1690 NSF), Room 00110 (93 NSF), Room 00115 (694 NSF), Room 00116 (1845 NSF), Room 00207 (724 NSF), Room 00225 (153 NSF), Room 00226 (153 NSF), Room 00227 (125 NSF), Room 00228 (123 NSF), Room 00301 (2177 NSF), Room 00218 (700 NSF), Room 00219 (963 NSF), Room 00220 (879 NSF), Room 00209 (1527 NSF), Room 00210 (878 NSF), Room 00214 (669 NSF), Room 00216 (788 NSF), Room 00217 (860 NSF), Room 00205 (1372 NSF), Room 00112 (733 NSF), Room 00113 (1657 NSF), Room 00203 (950 NSF), Room 00106 (1777 NSF), Room 00111 (1679 NSF), Room 00114 (18 NSF), Room 00206 (15 NSF), Room 00117 (17 NSF), Room 00217A (17 NSF), Room 00215 (20 NSF), Room 00211 (24 NSF), Room 00208 (16 NSF), Room 00107 (266 NSF), Room 00108 (38 NSF), Room 00109 (36 NSF), Room 00204 (29 NSF), Room 00219A (17 NSF)	\$2,686,140.00		

FLORIDA COLLEGE SYSTEM
PROJECT PRIORITY LIST REPORT
TALLAHASSEE COMMUNITY COLLEGE

Project Number: 1		No Comments Provided			
Project Number	Priority Ranking	Description	Estimated Cost	Status	Completed Date
1	A	Site: 4 CAPITOL CENTER Survey Recommendation: 4.007 Renovating Building Number - 1, Building Name - CAPITOL CENTER (48 SS), (38617 NSF) Apply Painting, Floor Cover, Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other to Room 00112 (386 NSF), Room 00114 (6500 NSF), Room 00116 (137 NSF), Room 00117 (185 NSF), Room 00118 (529 NSF), Room 00118A (215 NSF), Room 00200 (750 NSF), Room 00201 (120 NSF), Room 00202 (881 NSF), Room 00203 (526 NSF), Room 00207 (150 NSF), Room 00208 (745 NSF), Room 00210 (795 NSF), Room 00211 (1295 NSF), Room 00212 (750 NSF), Room 00213 (860 NSF), Room 00214 (1000 NSF), Room 00215 (166 NSF), Room 00216 (80 NSF), Room 00217 (80 NSF), Room 00218 (80 NSF), Room 00219 (1014 NSF), Room 00220 (60 NSF), Room 00221 (60 NSF), Room 00222 (200 NSF), Room 00223 (300 NSF), Room 00300 (6000 NSF), Room 00301 (180 NSF), Room 00303 (150 NSF), Room 00307 (225 NSF), Room 00308 (386 NSF), Room 00310 (850 NSF), Room 00311 (180 NSF), Room 00312 (676 NSF), Room 00313 (1870 NSF), Room 0B100 (78 NSF), Room 0B101 (1179 NSF), Room 0B102 (121 NSF), Room 0B103 (169 NSF), Room 0B104B (154 NSF), Room 0B104C (244 NSF), Room 0B105 (254 NSF), Room 0B106 (73 NSF), Room 0B107 (265 NSF), Room 0B111 (1025 NSF), Room 0B112 (348 NSF), Room 0B113 (149 NSF), Room 0B114 (554 NSF), Room 0B116 (153 NSF), Room 0B118 (180 NSF), Room 0B118A (25 NSF), Room 0B118B (25 NSF), Room 0B118C (25 NSF), Room 0B118D (25 NSF), Room 0B118E (25 NSF), Room 0B118F (25 NSF), Room 0B118G (25 NSF), Room 0B118H (25 NSF), Room 0B118I (25 NSF), Room 0B118J (25 NSF), Room 0B118K (25 NSF), Room 0B118L (25 NSF), Room 0B118M (25 NSF), Room 0B118N (25 NSF), Room 0B118O (25 NSF), Room 0B118P (40 NSF), Room 0B118Q (40 NSF), Room 0B118R (40 NSF), Room 0B118S (40 NSF), Room 0B118T (40 NSF), Room 0B118U (40 NSF), Room 0B119 (358 NSF), Room 0B120 (62 NSF), Room 0B121 (159 NSF), Room 0B122 (397 NSF), Room 0B123 (155 NSF), Room 0B124 (324 NSF), Room 0B125 (121 NSF), Room 0B126 (117 NSF), Room 0B127 (99 NSF), Room 00100 (752 NSF), Room 00102 (42 NSF), Room 00103 (768 NSF), Room 00105 (72 NSF), Room 00107 (40 NSF), Room 00108 (750 NSF), Room 0B108 (459 NSF)	\$3,475,530.00		

FLORIDA COLLEGE SYSTEM
PROJECT PRIORITY LIST REPORT
TALLAHASSEE COMMUNITY COLLEGE

Project Number: 1		No Comments Provided			
Project Number	Priority Ranking	Description	Estimated Cost	Status	Completed Date
1	A	Site: 5 GHAZVINI CENTER FOR Survey Recommendation: 5.012 Renovating Building Number - 1, Building Name - GHAZVINI CENTER FOR (570 SS), (30481 NSF) Apply Electrical, Plumbing, Windows, Lighting, Restrooms, HVAC Systems, Bell/Fire Alarm Systems, Retrofit for Technology, Other, Painting, Floor Cover to Room 00116 (102 NSF), Room 00124 (386 NSF), Room 00246A (120 NSF), Room 00242 (986 NSF), Room 00226 (2041 NSF), Room 00227 (1813 NSF), Room 00228 (1633 NSF), Room 00229 (1679 NSF), Room 00230 (2164 NSF), Room 00241 (1815 NSF), Room 00121 (1181 NSF), Room 00121A (75 NSF), Room 00121B (100 NSF), Room 00105 (982 NSF), Room 00107 (899 NSF), Room 00108 (825 NSF), Room 00109 (2270 NSF), Room 00110 (1601 NSF), Room 00111 (1602 NSF), Room 00204 (520 NSF), Room 00123 (1186 NSF), Room 00123A (75 NSF), Room 00128 (1167 NSF), Room 00129 (1199 NSF), Room 00130 (1237 NSF), Room 00131 (1522 NSF), Room 00128A (134 NSF), Room 00127 (1167 NSF)	\$2,743,290.00		
1	A	Survey Recommendation: SR.01 Correct deficiencies relating to safety to life, health, and sanitation as identified in the comprehensive Safety Inspection Report pursuant to §4.4(1) and §5(1) SREF.	\$350,000.00		
1	A	Survey Recommendation: SR.02 Necessary modifications for the physically disabled in existing buildings recommended for continued use as provided for in §255.21 F.S.	\$100,000.00		
1	A	Survey Recommendation: SR.03 Replacement of roofs at existing facilities as provided in §1.2(55) SREF and §423.12 Florida Building Code.	\$350,000.00		
1	A	Survey Recommendation: SR.04 Replace or purchase of equipment for existing facilities pursuant to §1.2(55) SREF.	\$360,000.00		

FLORIDA COLLEGE SYSTEM
PROJECT PRIORITY LIST REPORT
TALLAHASSEE COMMUNITY COLLEGE

Project Number: 1		No Comments Provided			
Project Number	Priority Ranking	Description	Estimated Cost	Status	Completed Date
1	A	Survey Recommendation: SR.05 Provide for sanitation facilities for students, staff, and the public pursuant to §5(1) SREF and §423.2 Florida Building Code.	\$85,000.00		
1	A	Survey Recommendation: SR.06 Provide for custodial facilities pursuant to §423.20 Florida Building Code.	\$150,000.00		